

JUN 14 1990

Ms. Carla McNabb, Property Manager  
Sanyo North America Corporation  
1751 Sheridan Street  
Richmond, Indiana 47374

EPA Region 5 Records Ctr.



348898

RE: Operation & Maintenance Inspection  
Sanyo North America Corporation  
NPDES Permit No. IN 0049972  
April 25, 1990

Dear Ms. McNabb:

On April 25, 1990, Mr. Gary Thevenow, of this office, conducted an Operation and Maintenance Inspection of Sanyo North America Corporation wastewater treatment facilities. The results of that inspection revealed the following areas of concern to this office:

1. Please explain high oil/grease values reported on your non-contact cooling water. Also what does the company plan to do to prevent future violations?
2. Please explain how flow is being estimated. The NPDES permit calls for instantaneous flow measurement when sampling. This would require a primary device for proper reporting.
3. The contract laboratory will need to provide a QA/QC manual and to improve recordkeeping. Please refer to NPDES Permit IN 0049972 under "Recording of Results".

It is requested that a written response be submitted to this office within twenty (20) days of the date of this letter as to the action taken to rectify the above-mentioned problems.

If you have any questions regarding this matter, please feel free to contact Mr. Gary Thevenow at 317/243-5137.

Very truly yours,

Stephen H. Boswell, Chief  
Surveys Section  
Office of Water Management

GVT/bs

cc: Wayne County Health Department

bcc: Steve Wolfe

GVT

1126b 05-07-90

final 05-17-90